

SECTION V - HEALTH HAZARD DATA

THRESHOLD LIMIT VALUE

135 ppm

EFFECTS OF OVEREXPOSURE

Anaesthetic effect. Lack of coordination, poor judgement, light-headed or dizzy. Unusually severe exposure may cause unconsciousness.

EMERGENCY AND FIRST AID PROCEDURES

Prompt removal from exposure. Call a physician immediately.

SECTION VI - REACTIVITY DATA

STABILITY

UNSTABLE

CONDITIONS TO AVOID

STABLE

X

INCOMPATIBILITY (Materials to avoid)

Strong oxidizing agents.

HAZARDOUS DECOMPOSITION PRODUCTS

Phosgene, hydrogen chloride, and carbon monoxide

HAZARDOUS
POLYMERIZATION

MAY OCCUR

CONDITIONS TO AVOID

WILL NOT OCCUR

X

SECTION VII - SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED

Confine to smallest area, do not allow runoff to enter sewers, streams, etc. Keep persons out of high vapor areas. Recover spills in drums or tanks, or absorb in sawdust and remove.

WASTE DISPOSAL METHOD

Same as for perchloroethylene

SECTION VIII - SPECIAL PROTECTION INFORMATION

RESPIRATORY PROTECTION (Specify type)

Canister with organic vapor cartridge.

VENTILATION

LOCAL EXHAUST

SPECIAL

MECHANICAL (General)

OTHER

PROTECTIVE GLOVES

PVa Gloves

EYE PROTECTION

Safety glasses, goggles, or face shield

OTHER PROTECTIVE EQUIPMENT

Rubber apron and protective work shoes.

SECTION IX - SPECIAL PRECAUTIONS

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING

Avoid breathing vapors and contact with skin. Keep away from sparks, glowing surfaces, and open flame.

OTHER PRECAUTIONS